

RFI104

Project: COOLEY LABORATORY RENOVATION
Job: 3146 COOLEY LAB, PPA# 10-0023
Customer: STOFMT MSU BOZEMAN
Issued To: CONSTRUCTION MANAGEMENT SERV.
P.O. BOX 7274
BOZEMAN, MT 59715

POTENTIAL IMPACTS
Cost Impact: No
Schedule Impact: No

Attention: DONALD J. PLATISHA
Phone/Fax: 406 585-0611 / 406 585-2698

Coordination copies to:

Item: EAST STAIRWELL DOORS
Reference: A9.3, A9.4, A1.3, A1.5, A1.7, A1.9
Attachments:

Type: ARCH/STRUC

Spec. Section:

Description of Request

QUESTION:
Door frames 101, 201, 301, and 401 were scheduled to receive a 4 inch jamb on the east side of the door. These doors were built wrong and the 4 inch jamb was placed on the west side of the door frame. We would propose to provide a new F-3 frame which does not have the 4 inch jamb and grout these doors solid so any gap between jamb and existing wall appears to be an extension of the existing wall. Please verify if this solution is acceptable?

Respond By: 03/29/12 By: TIM THOLT

Response

DAC's proposed solution is acceptable. Insure that the frames are coated with bitumen or equivalent to minimize potential corrosion from the grouting process.

Signed: F. J. di Stefano

Date: 3-22-12

Proceed as Indicated: _____

Date: _____

Owner Authorized Representative