

RFI 49

Project: COOLEY LABORATORY RENOVATION
Job: 3146 COOLEY LAB, PPA# 10-0023
Customer: STOFMT MSU BOZEMAN
Issued To: CONSTRUCTION MANAGEMENT SERV.
P.O. BOX 7274
BOZEMAN, MT 59715

POTENTIAL IMPACTS
Cost Impact: Yes
Schedule Impact: No

Attention: DONALD J. PLATISHA
Phone/Fax: 406 585-0611 / 406 585-2698

Coordination copies to:

Item: Missing Anchor Supports in Knee Braces Type: ARCH/STRUC
Reference: 6/3.0 Spec. Section:
Attachments:

Description of Request

QUESTION:
The two anchor bolts on the furthest east/west knee braces on the south and north elevation do not penetrate into concrete, as they are in the void space between the brick facade and the concrete wall on the east and west elevation.

Respond By: 10/26/11 By: TIM THOLT

Response

The two expansion bolts are not required structurally.

Jerome Gannon 10/20/11

Signed: _____ Date: _____

Proceed as Indicated: _____ Date: _____

Owner Authorized Representative