DICK ANDERSON CONSTRUCTION,INC

Number: 42

Date Issued: 09/30/11

						
RFI 42						
Project: RENOVATION	COOLEY LABORATORY		POTENTIAL IMPACTS Cost Impact: No			
Job:		3146	COOLEY LAB, PPA# 10-0023	add. No	Schedule Impa	
Customer:		STOFMT	MSU BOZEMAN			
Issued To:		CONSTRUCTION MANAGEMENT SERV. P.O. BOX 7274 BOZEMAN, MT 59715				
Attention: Phone/Fax:	406 585-0611 / 406 585-2698	DONALD J. PLATISHA		Coordination co	Coordination copies to:	
•		=>#			T	
Item:		EXHAUST DUCT OFFICE 315			Type: MECH	
Reference:		M2.3.1		Spec. 9	Section:	
Attachments:						
					De	
QUESTION: Why is there a	an exhaust duct in office 315 but this office?	no exhaust duct in th	ne other offices on the second f	loor? Is a phoenix valve	SAV 315	
necessary for	this office?			·		
Respond By:		10/12/11	By: TIM THOLT			
		D	esponse			
The second floc offices are so sr	or offices are served by two supp mall that individual valves and V	oly valves (SAV-204/2 AV controls were not	13) and two exhaust valves (GI necessary. Both SAV-315 and	EX-214/219. The loads in GEX-315 are required fo	the second floor r office 315.	
	Signed	: Michael Bender, GPD		Date: 10	/7/2011	
	Signed	: Michael Bender, GPD		Date: <u>10</u>	/7/2011	