DICK ANDERSON CONSTRUCTION, INC

Number: 110


Date Issued:	04/10/12
Date Issueu.	0 1/ 10/ 12


						Date Issued:	04/10/12
RFI 110							
Project:	COOLEY LABORAT	TORY RENO	 VATION		POTENTIAL IMPACT	s	
Job:	3146 CC	OOLEY LAB,	PPA# 10-0023		Cost Impact: No		
Customer:	STOFMT MS	SU BOZEMA	N		Schedule Impact: No		
Issued To:	CONSTRUCTION I P.O. BOX 7274 BOZEMAN, MT 597		NT SERV.				
Attention: hone/Fax:	DONALD J. PLATIS 406 585-0611 / 4			Coordination copies to:			
Item:	W Beam at New Sta	air Landings		Type: ARC	CH/STRUC		
Reference: Attachments:	9/\$3.1			Spec. Section:			
		to use a 3		Description of Request S3.1 shows the W Beam being c d in-lieu of the bolted connection?		te by bolted	j
espond by.	04/17/12	Бу. Т.	II IIIOEI				
It is peri		./16" fillet v	veld. Weld the	3/8" connection plate to the beam of	web three sides t	ур.	
		Sigr	ned:			Date:	

Owner Authorized Representative

Date:

Proceed as Indicated: __





STAIR LANDING DETAIL