DICK ANDERSON CONSTRUCTION, INC

RFI 141						
Project:	COOLEY LABORATORY RENOVATION				POTENTIAL IMPACTS	
Job:	3146 COOLEY LAB, PPA# 10-0023				Cost Impact: No Schedule Impact: No	
Customer:	STOFMT	MSU BOZEN	IAN			
Issued To:	CONSTRUC P.O. BOX 72 BOZEMAN, I		IENT SERV.			
Attention:	DONALD J. F	PLATISHA		Coordination copies to:		
Phone/Fax:		11 / 406 585-26	98			
Item:	DEAD BOLT	S ON WEST AC	CESS DOORS	Туре: А	RCH/STRUC	
Reference:	08710 Hardw	are Group H-4		Spec. Section:		
Attachments:						
Description of Request						
			•	pped for standard dead bolt with keyed acces . Is it permissible to utilize the provided alumi	ss. The specified dead bolt per spec section inum access door dead bolts and make them a	
Respond By:	09/11/12	By:	TIM THOLT			

Response

Yes. Insure that there is a trim ring. The thumb turn handles that I saw installed were not trimmed out and the raw edges of the drilled prep were visible.

Signed: F J di Stefano

Date: <u>9-4-12</u>

Date:

Proceed as Indicated: