## **DICK ANDERSON CONSTRUCTION, INC**

Number: 99

Date Issued: 03/15/12

RFI	99					
Project:	COOLEY LABO	ORATORY RENOVA	ATION		POTENTIAL IMPACTS	
Job:	3146	COOLEY LAB, PR	PA# 10-0023		Cost Impact: No Schedule Impact: No	
Customer:	STOFMT	MSU BOZEMAN			Concusto III pacti no	
Issued To:	CONSTRUCTION MANAGEMENT SERV. P.O. BOX 7274 BOZEMAN, MT 59715					
Attention:	DONALD J. PL	ATISHA		Coordination copies to:		
Phone/Fax:		/ 406 585-2698				
Item:	Door Handing	West Elevation	Type: ARCH/STRUC			
Reference:	A1.2, A1.4, A1	.6, A1.8,		Spec. Section:		
Attachments:						
			Doc	scription of Request		
QUESTION:						
What should	the handing o	n door 105, 203, 3	303, and 403 be?	Please note these doors wil	I swing out as they are	insulclad doors.
espond By:	03/22/12	ву: ТІМ Т	HOLT			
				Response		_
Timge	on the south sid	e of the frame and	wiii 3wiiig Out. Ii iii	y handing knowledge is correct	tins would make it a right	manu reversed manued door.
Signe	d: <u>FRANK JC</u>	HN DI STEFANO	)			Date: 3-16-12
		Proceed as	Indicated:			Date:
				r Authorized Representative		